



[Home](#) [About Us](#) [Services](#) [Projects](#) [Partners](#) [Contacts](#)

CPP Oil Distributor Shaft Repair



Project details

Categories:	Marine Parts Recovery by Laser Cladding
Date:	Mai 2016.
Project Object:	Passenger Ship CPP Oil Distributor Shaft
Project Description:	Repair of the neck, diameter 530 mm, worn out of limits
Repair Place:	Reneko workshop
Repair Time:	3 days
Class Survey:	BV
Warranty:	Yes, standard service warranty apply

Description of work

CPP oil distributor shaft was found in unacceptable condition due to excessive wear of the neck.
Reneko submitted repair procedure to the Class, prior to repair.
Repair was done in Reneko workshop, by laser cladding method.
All repair process, including final machining has taken 3 working days.
Work was accepted by Customer and Class without remarks.

After sale

Shaft was mounted back to the Ship at the end of repair.

Reneko Office

Open hours: Mon - Fri
08.00-16.30

Tel: (+372) 660 3479

Fax: (+372) 660 3486

e-mail: reneko@reneko.ee

Managing director/CEO

**Dipl. Ing. Klim
Kastjushin**

Tel: (+372) 5660 8572

(Est, Rus, Eng)

e-mail: klim@reneko.ee

Technical Supervisor/CTO

**Dipl. Ing. Vjacheslav
Kastjushin**

Tel: (+372) 509 4119

(Rus)

e-mail: vk@reneko.ee

Workshop Manager

Roman Bunkov

Tel: (+372) 5554 4015

(Est, Rus, Eng)

e-mail: workman@reneko.ee