




[Home](#) [About Us](#) [Services](#) [Projects](#) [Partners](#) [Contacts](#)

## ABB VTR-454 Turbocharger Rotor Shaft, necks repair



### Project details

Categories:	<b>Turbocharger Rotors</b>
Date:	June 2017.
Project Object:	ABB VTR-454 Turbocharger Rotor Shaft
Project Description:	Repair of the weared necks on the shaft
Repair Place:	Reneko workshop
Repair time:	2 days.
Factory Warranty:	Yes. Standard service warranty applicable.

### Description of work

On the VTR-454 Turbocharger Rotor there was found a shaft necks wear.  
Reconditioning was done by Laser Cladding method in Reneko workshop.

### After sale

#### Reneko Office

Open hours: Mon - Fri  
08.00-16.30

Tel: (+372) 660 3479

Fax: (+372) 660 3486

e-mail: [reneko@reneko.ee](mailto:reneko@reneko.ee)

#### Managing director/CEO

**Dipl. Ing. Klim  
Kastjushin**

Tel: (+372) 5660 8572

(Est, Rus, Eng)

e-mail: [klim@reneko.ee](mailto:klim@reneko.ee)

#### Technical Supervisor/CTO

**Dipl. Ing. Vjacheslav  
Kastjushin**

Tel: (+372) 509 4119

(Rus)

e-mail: [vk@reneko.ee](mailto:vk@reneko.ee)

#### Workshop Manager

**Roman Bunkov**

Tel: (+372) 5554 4015

(Est, Rus, Eng)

e-mail: [workman@reneko.ee](mailto:workman@reneko.ee)