



[Home](#) [About Us](#) [Services](#) [Projects](#) [Partners](#) [Contacts](#)

## MAK 25 Cylinder Covers lower O-belt Reco



### Project details

Categories:	4-stroke motors Cylinder Covers
Date:	Dec-2016.
Project Object:	ME MAK 25 Cylinder Covers 8 pcs
Project Description:	Cylinder Covers, all 8 pcs, had corrosion wear in place of lower O-ring seal
Repair Place:	Reneko workshop
Repair Time:	1 Week
Warranty:	Yes

### Description of work

ME MAK 25 cylinder covers were subjected NO-GO for the further use because of critical corrosion wear in place of lower O-belt. Replacement or Reco was required to complete engine overhaul. Ship Management has chosen Reco instead of replacement as a cost-effective solution. Reco was done in Reneko workshop. Corrosion was eliminated completely by pre-machining and, after that, a new corrosion-resistant material was applied. Post-machining was done to original design shape.

### After sale

Cylinder covers, all 8 pcs, were installed back to the engine immediately after repair. Currently in operation.

#### Reneko Office

Open hours: Mon – Fri  
08.00-16.30

Tel: (+372) 660 3479

Fax: (+372) 660 3486

e-mail: [reneko@reneko.ee](mailto:reneko@reneko.ee)

#### Managing director/CEO

**Dipl. Ing. Klim  
Kastjushin**

Tel: (+372) 5660 8572

(Est, Rus, Eng)

e-mail: [klim@reneko.ee](mailto:klim@reneko.ee)

#### Technical Supervisor/CTO

**Dipl. Ing. Vjacheslav  
Kastjushin**

Tel: (+372) 509 4119

(Rus)

e-mail: [vk@reneko.ee](mailto:vk@reneko.ee)

#### Workshop Manager

**Roman Bunkov**

Tel: (+372) 5554 4015

(Est, Rus, Eng)

e-mail: [workman@reneko.ee](mailto:workman@reneko.ee)