

Voyage repair of CPP blades, Norway



Project details

Categories:	Voyage Repairs of Propellers
Date:	Mar 2013.
Project Object:	CPP blades voyage repair
Project Description:	Damaged CPP blades voyage repair in Shipyard workshop
Repair Place:	Halsnøy Dokk Shipyard
Repair Time:	1 Week
Class Survey:	DNV
Warranty:	Yes, standard service warranty apply

Description of work

Repair of CPP blades, damaged by ground impact, was done in Halsnøy Shipyard by Reneko voyage team, under supervision of DNV Class.

Propeller blades were dismantled and delivered to Shipyard workshop. Reneko team made straightening to right geometry and welding repair in order to rebuild missing areas. After that blades were final machined, weights were adjusted, normal polishing was done. Repair was accepted by Class in full, with no remarks. Repair has taken 1 Week in total.

After sale

Blades were installed back to the Ship at the end of repair.

We had a chance to monitor the blades few years after repair, during Ship next planned DD, in Tallinn. No problems has been observed.

Reneko Office

Open hours: Mon – Fri
08.00-16.30

Tel: (+372) 660 3479

Fax: (+372) 660 3486

e-mail: reneko@reneko.ee

Managing director/CEO

**Dipl. Ing. Klim
Kastjushin**

Tel: (+372) 5660 8572

(Est, Rus, Eng)

e-mail: klim@reneko.ee

Technical Supervisor/CTO

**Dipl. Ing. Vjacheslav
Kastjushin**

Tel: (+372) 509 4119

(Rus)

e-mail: vk@reneko.ee

Workshop Manager

Roman Bunkov

Tel: (+372) 5554 4015

(Est, Rus, Eng)

e-mail: workman@reneko.ee