

Yanmar N21-A2 Cylinder Covers, 2 pcs, exhaust pockets Reco



Project details

Categories:	4-stroke motors Cylinder Covers
Date:	Nov 2016.
Project Object:	Yanmar N21-A2 Cylinder Cover, 2 pcs
Project Description:	Reco of exhaust pockets, worn out of limits
Repair Place:	Reneko workshop
Repair Time:	1 Week
Warranty:	Yes, standard service warranty apply.

Description of work

Cylinder covers, 2 pcs, was found in NO-GO condition in place of exhaust pockets.

Exhaust pockets were touched by corrosion and out of dimensional tolerance.

Reneko performed Reco of exhaust pockets to original size.

After that, cylinder cover was overhauled with NEW parts: central sleeve, valve guides, valve seats, and delivered back to the Customer

After sale

Reneko Office

Open hours: Mon – Fri
08.00-16.30

Tel: (+372) 660 3479

Fax: (+372) 660 3486

e-mail: reneko@reneko.ee

Managing director/CEO

**Dipl. Ing. Klim
Kastjushin**

Tel: (+372) 5660 8572

(Est, Rus, Eng)

e-mail: klim@reneko.ee

Technical Supervisor/CTO

**Dipl. Ing. Vjacheslav
Kastjushin**

Tel: (+372) 509 4119

(Rus)

e-mail: vk@reneko.ee

Workshop Manager

Roman Bunkov

Tel: (+372) 5554 4015

(Est, Rus, Eng)

e-mail: workman@reneko.ee