

Wartsila 32 Mahle pistons Reco, 6 pcs



Project details

Categories:	4-stroke motors Pistons
Date::	Mai 2017.
Project Object::	Wartsila 32 pistons Mahle, 6 pcs
Project Description::	Reco of contact surfaces on crown and skirt, weared out of limits
Repair Place::	Reneko workshop
Repair Time:	2 Weeks
Factory Warranty:	Standard service warranty apply

Description of work

Wärtsila 32 Mahle pistons, 6 pcs were found in NO-GO condition due to pitting wear on contact surfaces on crown and skirt.

Plating on contact surface of piston skirt was removed, crack detection was done, contact surface was re-plated and re-machined to original size. Piston crown contact surfaces were reconditioned to original size. Hidden gap was adjusted, measured and recorded.

After sale

Reneko Office

Open hours: Mon – Fri

08.00-16.30

Tel: (+372) 660 3479

Fax: (+372) 660 3486

e-mail: reneko@reneko.ee

Managing director/CEO

Dipl. Ing. Klim

Kastjushin

Tel: (+372) 5660 8572

(Est, Rus, Eng)

e-mail: klim@reneko.ee

Technical Supervisor/CTO

Dipl. Ing. Vjacheslav

Kastjushin

Tel: (+372) 509 4119

(Rus)

e-mail: vk@reneko.ee

Workshop Manager

Roman Bunkov

Tel: (+372) 5554 4015

(Est, Rus, Eng)

e-mail: workman@reneko.ee